



Ken Robbins
Highway Administrator

702 K St.
Belleville, KS 66935

Phone: (785) 527-2235


Fax: (785) 527-5335

Weekly Report to Commissioners

PROPOSED 14,000 SF NEW SHOP

County maintains 9.6 million in equipment assets which include:

- 121 pieces of equipment
- 81 light and heavy rolling stock
- Current Shop was built in 1929
- Smaller than any neighboring county shop.
 - No Washdown Bay
 - No Tire Service Bay
 - No Operator Service Bay
- New shop would allow another mechanic to be hired, allowing more work to be performed in-house, saving operating dollars.
- Rough order of magnitude estimate is that this project would require 2-3 million dollars.
- 1.1 million already reserved for this project; an additional 1.2 million possible from the State for assuming maintenance responsibilities for 2 miles of State Roads.



- Department is seeking approval from the Commission to proceed beyond conceptual drawings to biddable construction documents so that an accurate project estimate can be developed.



- Detailed construction documents could allow procurement and construction methods that include the County performing some of the work, reducing overall costs.

Community Concerns

ID	Description	Notes/Progress/Resolution	Status
Administration			
132	170 Road .0-.8 mile south of US-36; road & drainage improvements are needed.	Investigating solutions and impacts on adjacent properties	Open
45	Norway Lane; drainage improvements are needed.	KDOT is preparing a scope of work to improve KS-148 that passes through the community of Norway. This should significantly Improve drainage in the area.	Open
Construction			
119	130 RD .55 West of Zeal RD South side; Trees/Brush need removed;	Utilities have been located. Landowner agrees to tree pile placement on his property.	Open
135	Bridge T-22.7 (6-ton load limit) on Timber Road .7 mile east of 220 Road has sustained damage from an oversized load that broke through the deck.	Completed	Closed
136	Queen Road .75 mile east of 30 Road on the north side; the Ditch needs cleaned of Brush and trees for .25 mile to 40 Road.		Open
137	150 Road .17 mile north of US-36, on the west side of the road; a driveway needs improved.	Extend culvert 10ft on the south side, regrade to remove eyebrow at the entrance.	Open
138	Fir Road .67 mile east of 220 Road; a culvert under the road needs replaced.		Open
139	180 Road and Marble Road intersection; a sight obstruction was reported on the NW corner of the intersection.	Investigating	Open
140	Rock Road .25 miles east of 90 Road on the north side; Landowner requesting a new driveway be installed.	New 18"x30' CMP needed	Open
141	At the T intersection of 90 Road and Rock Road on the west side; a driveway needs replaced.	Landowner requesting the narrow 2'x15' concrete box be removed. Replace with a 24"x30' CMP	Open
142	Nickel Road .6 mile west of 150 Road on the south side a new Culvert needs installed'	Install a new 18"X40' CMP Culvert.	Open
144	170 Road .6 Miles north of Fir Road on the west side; Landowner is requesting a new driveway.	Install a new 24"x30' CMP	Open
145	Granite Road .4 miles west of 170 Road on the south side; Landowner is requesting ditches be cleaned and the driveway culvert be improved.	Investigating	Open
148	Birch Road.25 miles east of 110 Road on the north side; Landowner requesting plugged culvert be replaced.	New 18"x30' CMP needed	Open
150	Ash Road .5 miles east of 100 Road on the south side; Landowner requesting a new driveway.	18"x 40' CMP requested	Open
52	70 Road between US36 and Queen Road; Drainage improvements are needed on both sides of the Road	60% Completed overall. Drainage improvements will continue after harvest.	Open
Maintenance			
146	160 Road .75 miles north of Diamond Road on the west side; Ditch needs cleaned.	Landowner requesting the ditch be cleaned for .25 miles to install new fence, also place rip-rip around the box culvert to prevent scouring.	Open
149	Queen Road .1 mile west of 130 Road on the north and south side; ditch cleaning requested.	Investigating	Open
151	260 Road north of King Road; Report of road being scoured and rough.	Completed	Closed

Community Concerns, *continued*

ID	Description	Notes/Progress/Resolution	Status
50	30 Road improvements are needed to restore the crown in the roadway between Highway 36 and Fir Road.	4 miles have been completed.	Open
53	60 Road between Elm and Ash Roads needs the shoulders pulled and fortified with rock and econo-base then finished with gravel.	2 miles have been completed.	Open
152	230 Road between Queen Road and Rock Road; Report of being rough and scoured.	Completed	Closed

Upcoming Events

1. Annual Report on High Banks Wind Energy/NextEra Agreement compliance issues.
2. Right-of-Way vacations for a portion of Seapo Trail in Section 21 of Grant Township and for the SW corner of Section 35 in Liberty Township (old Marble/US81 intersection ROW) are being prepared for Commission consideration.