



Ken Robbins
Highway Administrator

702 K St.
Belleville, KS 66935

Phone: (785) 527-2235

Fax: (785) 527-5335

Weekly Report to Commissioners

Community Concerns

Culvert Installation/Replacement Requests:

- 250 Road 200' north of K148; a concrete tile culvert under the road has come apart and will be replaced with a 48" x 40' CMP culvert.

Other Concerns:

- Granite Road at Jewell Lane; debris from tree grinding plugged a culvert under granite west of the intersection. *Completed; debris have been removed*
- 20 Road just north of Oak Road on the east side; material from the back slope of a ditch was borrowed to lift the road during a culvert replacement. There is now a concern that runoff will top the backslope and enter the field, causing erosion. *An investigation has confirmed this, and it will be corrected.*
- 300 Road .3 miles north of K-148; the top 90 of a step drain culvert failed under the road and must be replaced or repaired. The sink hole has been filled temporarily.
- Shady Road west of 30 Road, concerns have been expressed about a driveway from an irrigation canal right of way draining onto the road and what improvement the property owner and the County to make to improve the situation.
- 20 Road between Queen and Rock Road, improvements are needed. Water is ponding on the road.

Department Reports on Non-Routine Activities

Roads and Bridges

- Hot asphalt repairs of potholes continued ahead of sealing proposed for 290, 180 and 50 Roads south of K148 late this summer. The cold recycled asphalt overlay south of Scandia for the first mile is being rescheduled due to a supplier challenge.
- Max Wickstrum has agreed to accept the responsibility of maintaining District 3 north of Belleville. This includes Freedom and Liberty Townships.
- Transportation Department Bus Inspections were conducted by KDOT on June 17. We have some suspension and exhaust improvements that need to be made before next year's inspection, but no issues that will affect services to the Community.

PENDING ACTIONS IN RESPONSE TO COMMUNITY CONCERNS

Bridge and Culverts Division Project List (in order of priority)

1. Norway Lane: drainage improvements are needed.

Roads and Driveways Division Project List (in order of priority)

1. Rock Road between 30 & 50 Roads; a regrade, ditch cleaning and improved gravel finish may be necessary.
2. Gravel is requested for a half mile of Diamond Road west of 310 Road. *This work will be performed with reclaimed material from the wind farm project when it becomes available soon.*
3. Residents north of Fir Road on Republic Lane are requesting improvement of the road base with larger gravel or rock. The fine sand common to the area becomes tracked up easily when it is wet.
4. 210 Road south of Nickel; .1 mile is graveled from Nickel to a residence and .6 mile is graveled from US 36 north. A resident is requesting that the remaining .3 mile be graveled for direct access to Nickel where a number of residents live. **Completed**
5. 100 Road .28 mile south of Timber Road on the west side; a 30" squash crossroad pipe has been cleaned out transferring runoff from acreage on the east side to a shallow ditch on the west side that cannot get through a plugged culvert several hundred feet to the south. The farmer believes most of the runoff could stay on the west side with some ditch cleaning. *investigating*
6. Queen Road, west of 20 Road, tree removal, ditch cleaning and driveway upgrades needed for the first .5 mile. *40 ft driveway installed; some ditch cleaning still needed.*
7. Queen Road west of 230 road for .25 mile on the south side; the right-of-way needs to be cleared for a new fence.
8. 80 Road .5 miles south of Shady Road on the west side; trees/brush need to be removed from the right-of-way. **Completed**
9. Penn Road, east of Scandia on the south side; trees/brush need to be removed from the right-of-way.
10. 30 Road improvements to restore the crown in the roadway between Highway 36 and Fir Road. *4 miles have been completed.*
11. *70 Road south of US 36 Highway has been prepared to receive recycled asphalt paving. A schedule and cost sharing plan for Paving will be prepared by the Highway Administrator for the Commission and Property Owners to consider.*
12. *Cut and patch 4-6ft of Concrete at 170 Road near residence 1549 (Primary Road; Currently 23x23 & 10x23 inch potholes where previous asphalt patch has failed). A hot asphalt patch is being tested at this location.*

Upcoming Events

1. U.S. Senator Roger Marshall, M.D. announced \$1,520,000 in grant funding to the North Central Regional Planning Commission from the U.S. Department of Transportation's Safe Streets and Roads for All (SS4A) grant program.
 - a. *The Highway Administrator is communicating with the North Central Region Planning Commission (NCRPC) about what this means for Republic County. Representatives for the NCRPC do not know yet but hope to bring all the member counties together within the next 60-90 days to consider next steps.*
2. Vacations of Right-of-Ways are proposed for 3 road spurs adjacent to Highway 81 that were abandoned after improvements to the Highway many years ago.